

**DPC Trustees Meeting
November 2015**

Trustees in attendance: Steve Bohn, Larry Scherr, Chester Harris, Reiff Lorenz
Trustees absent: Gary Wheeler

Membership:

Treasurer:

We have a few members in arrears; they will be contacted. We are looking into closing the PO box to save the club money. A new address will be provided. We will be moving the checking account to a bank that has more than 2 branches.

The flying rates of the planes will be adjusted to account for higher maintenance costs and lower fuel expenses. The new rates will be \$95/hr for the Archer and \$140/hr for the 182 effective December 1st.

We are suspending the dues credits for all trustees and crew chiefs until further notice.

Safety:

N199TX:

The reported problems with the electric fuel pump could not be replicated. The tires were checked, and are within their operating limitations.

N8078X:

We're looking into the persistently intermittent problem with the fuel gauge. Some experimentation indicates that the fuel float sensor is the culprit. It will be replaced. The battery was slowly dying, and the audio panel was the first electrical device to fail as the voltage dropped. The battery has been replaced. The tire was reported to have a slow leak. It will be checked.